

US EPA ARCHIVE DOCUMENT

<b>UNIT LOG</b>	1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 03/30/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit	5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 03/29/12 – 0700, 04/12/12
7. Personnel Roster Assigned			
Name		ICS Position	Home Base
Matthew Haak		Situation Unit Leader	Houston, Texas
8. Activity Log			
Time	Major Events		
09:00	Operational status: <ul style="list-style-type: none"> <li>• OB10.37, sheen observed.</li> <li>• MP17.0 LDB RockTenn, sheen observed within boom.</li> <li>• Talmadge Creek entering into the confluence, no sheen or turbidity observed.</li> <li>• Confluence, no turbidity or sheen observed.</li> <li>• Talmadge Creek south of A Drive, no turbidity or sheen observed.</li> <li>• Frac-City, timber mats observed being shredded.</li> </ul>		
	Additional observations: None		
15:00	Return to ICP.		
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START			